

Additional Funding Request

MD002	CSS# 18085 WO# 8012 Asset# NA														
Description of Repairs	Labor and materials to install an access hatch in ceiling needed to access inop tankless water heater that requires troubleshooting. Upon troubleshooting, we will then know whether repair or replacement is necessary.														
Diagnosis: Initial Work Order	Restore hot water to the OMS build														
Diagnostic Cost	<p>\$ 160</p> <p>TW – 2hrs @ \$80/hr</p>														
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>TW – 6hrs @ \$80/hr</p>														
Additional Material Cost to Perform Repairs	<p>\$101.44</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Access Door - 2VE74</td> <td style="width: 10%;">1</td> <td style="width: 10%;">\$96.61</td> <td style="width: 10%;"></td> <td style="width: 10%;">\$96.61</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td></td> <td>\$4.83</td> </tr> </table>					Access Door - 2VE74	1	\$96.61		\$96.61	Sales Tax				\$4.83
Access Door - 2VE74	1	\$96.61		\$96.61											
Sales Tax				\$4.83											
Total Cost of Repair	\$ 741.44														



WORK ESTIMATE

CSS #:

18085

Work Order #:

8012

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	New OMS
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to install an access hatch in ceiling needed to access inop tankless water heater that requires troubleshooting. Upon troubleshooting, we will then know whether repair or replacement is necessary.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Repair Labor			6	\$480.00
Access Door - 2VE74	1	\$96.61		\$96.61
Sales Tax				\$4.83
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$101.44	Labor \$640.00
		TOTAL		\$741.44

TOUGH GUY

GRAINGER CHOICE

Access Door with Drywall Flange, Flush Mount, Uninsulated

Item # 2VE74 Mfr. Model # 2VE74 Catalog Page # 2002 UNSPSC # 52171001

Web Price **\$80.51** / each One Time Delivery Shipping PickupExpected to arrive **Wed. Mar 20.**

Ship To 43065 (Change)

[+ Add to List](#)

Be the first to write a review

Shipping Weight **15.0 lbs.**Country of Origin **Canada** | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.
[More](#)



How can we improve our Product Images?

Compare

"WARNING"

DISCONNECT FROM POWER SUPPLY BEFORE REMOVING COVER.

BEFORE SWITCHING "ON" THE POWER SUPPLY AT THE CIRCUIT BREAKER, MAKE SURE THAT THE HOT WATER SYSTEM IS FREE OF ALL AIR POCKETS, OTHERWISE PREMATURE FAILURE OF THE ELEMENT WILL OCCUR. TO DO THIS, OPEN THE HOT WATER FAUCET FOR A MINUTE OR TWO UNTIL THE FLOW IS CONTINUOUS. NOW OPEN THE FAUCET FIVE TIMES ENSURING THAT THE INDICATOR LIGHT IS "ON" WHEN WATER IS FLOWING AND "OFF" WHEN IT IS NOT.

IF AT ANY TIME THE COLD WATER SUPPLY IS TURNED OFF, SWITCH "OFF" THE ELECTRICITY AND THEN REPEAT THE ABOVE PROCEDURE.
HOTTER WATER INCREASES THE RISK OF SCALD INJURY.
CONSULT THE INSTRUCTION MANUAL BEFORE CHANGING THE TEMPERATURE SETTING.

DO NOT SOLDER PIPE WHILE CONNECTED TO VALVE OR FAUCET FITTINGS.
DO NOT USE PIPE DOPE OR "T" FLOOR FLANGE ON VALVE OR FAUCET FITTINGS.
USE COMPRESSION SLEEVES OR FLANGE NUTS AND FLANGE WASHERS.

SERVICE QUESTIONS: 1-800-543-6163
HAVE MODEL NO. AND SERIAL NO. READY
www.eemax.com

