

Additional Funding Request

NY113	CSS# 22026 WO# 1563 Asset# NA							
Description of Repairs	Labor and materials needed to replace two (2) nonfunctional Card Readers.							
Diagnosis: Initial Work Order	Card reader back door of facility not working, and card reader at amsa shop not working urgent							
Diagnostic Fee	\$ 450 See attached invoice							
Additional Labor Cost to Perform Repairs	\$ 600 Labor \$75/hr x 8							
Additional Cost	\$ 396 <table border="1" style="width: 100%;"><tr><td style="width: 40%;">HID iClass readers</td><td style="width: 10%;">2</td><td style="width: 20%;">\$198.00</td><td style="width: 30%;">\$396</td></tr></table>				HID iClass readers	2	\$198.00	\$396
HID iClass readers	2	\$198.00	\$396					
Total Cost of Repair	\$ 1,446.00							

LoCurrent Systems, LLC

3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1483**DATE** 01/09/2020**P.O. NUMBER**

Mattydale, NY Replace Readers

	ACTIVITY	QTY	AMOUNT
01/09/2020	Services Follow Up Quotation to Inv 1563: CSS# 22026 Mattydale, NY USARC NY113 Replace (2) Readers	1	996.00

Dear Ms. Lee:

As per your request, LoCurrent Systems is pleased to provide a quotation to replace (2) nonfunctional Readers at the Mattydale, NY USARC NY113.

Cost Breakdown:

(2) HID iClass Readers.....\$396.00
(1) Man 8 hours
@\$75.....\$600.00

Grand
Total.....\$996.00

The cost for the above mentioned is \$996.00.

If acceptable, please do not hesitate to contact us so that we may scheduel for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,


ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$996.00

Accepted By

Accepted Date







WORK BAYS

HID

® **pivCLASS® RP40-H**
© 2012-2016 HID Global Corporation

All rights reserved. Made in US from imported Parts

Patented, www.hidglobal.com/patents

920PHRNEK00005

RP40EKNR RDR FW: VAS00137 REV M

2717-313268 PIV FW: VAS00300 REV B.1

SRD Model: RP40E PIV HW: VAS00301 REV A.1

FCC ID: JQ6-MCLASSRP40E SECURITY

IP55



LISTED

ACC RDR
NM

8T29



LISTED

TYPE G

Suitable for outdoor use.

Electrical ratings

TYPE S

Refer to Install Guide PLT-01134 Rev A.x

BEEP (YEL)	GPIO1 (I)
GRN (ORG)	GPIO2 (I)
GND (BLK)	OCT/TMR
+VDC (RED)	DATA1/I
DRAIN (BARE)	DATA0/I
RED (BRN)	
HOLD (BLU)	
GPIO3	