

**Additional Funding Request
REVISED
Additional Efforts**

Submitted: 1/15/2020

MD021 - NR Repair Mixer (HOBART) Electrical Issues	CSS #28446 WO#13464											
Description of Repairs	S&S proposes to remove and replace the timer knob/board on the Hobart mixer and will then complete a system check to make sure everything is running as intended.											
Original SC Investigative Diagnosis	\$800.89											
Diagnosis: Initial Work Order	Repair Mixer (HOBART) Electrical Issues											
Explanation of Additional Costs for Repairs	S&S proposes to remove and install the motor with the correct one for the unit. S&S will then complete a system check to make sure everything is running as intended.											
Additional Material Cost to Perform Repairs	<p>Materials: \$1,196.92</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Motor and shipping</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$1,196.92</td> <td style="text-align: left; padding: 2px;">\$1,196.92</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Motor and shipping	1	\$1,196.92	\$1,196.92
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Motor and shipping	1	\$1,196.92	\$1,196.92									
Additional Labor Cost to Perform Repairs	<p>Labor: \$300.00 Hot side Labor Rate/4 hours/Rate \$100.0 per hour = \$300.00</p>											
Total Cost of Repair	\$2,297.81											