



Boiler #2 - The safety or safety relief valve is not installed with the spindle in the vertical position. The safety or safety relief valve shall be re-piped so the spindle is installed in the vertical position. The discharge pipe shall be equal to or exceed the total cross sectional area of the safety relief valve discharge(s). Piping shall be installed and supported so as not to induce a strain on the safety valve(s).

Sentry called back for a Gas smell on Boiler # 2 & 3. These findings are for Boiler 2 only.

Boiler # 2 is not firing in low fire due to a cracked gas valve:

- Remove / install gas valve
- Start up
- Perform combustion analysis
- Start up
- Warranty

CMI Cost Estimate								
Funding Request								
PA017 Clearfield								
Boiler #2 is not firing								
CSS #17277 - CMI # 7523								
Prepared By: J. Bayne								
1.25.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	8						\$ 784.00
1.2 Modulating Gas Valve					\$ -	\$ -	\$ -	\$ 305.08
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 1,113.08
2. Initial Service Call Investigation								
Grand Total								\$ 1,113.08