

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

CUSTOMER PO. NO. _____

JOB NAME/LOCATION USARC - New River Valley Memorial **VA012**
SERVICE REQUESTED HW Pump.

Manufacturer: Other
Model#: SOLO 399
Serial#: PS69278

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested
- Leak Found
- Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

left it be. Then looked at the boiler on the right and it was getting power, but continuously purged and had no display. Looks like it could use a new control board. Then looked at the popoff issue and i do believe all it was is that the bypass valve for the make-up was open and was just over-pressurizing the loop. Turned it off and drained some water off of the loop and it was running good now. Can't do anything with the right boiler because it has a bad control board. Fired up all of the pumps at the 580 and took amp draws on them, leak checked, and check pressure diffs and they all looked good, expansion tank seemed to be OK, and bleeders on the boilers were working. Buttoned everything up after that, did paperwork, and then left.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative