

# Argent Inspections

## Form AI-03

## Boiler Inspection Report

Inspection Date 9/21/2020	Certificate Issued No	Expiration Date	Prepared for Inspection Yes	Next Watersides/Firesides 2022	Next Strength Test
Inspection Type(s) Performed <input type="checkbox"/> Internal <input type="checkbox"/> Watersides <input type="checkbox"/> Firesides <input checked="" type="checkbox"/> External/Operational <input checked="" type="checkbox"/> Pressure Test <input type="checkbox"/> Strength <input checked="" type="checkbox"/> Tightness					
Customer 99th RSC R2 Z1 NY054 USARC Plattsburgh			Boiler Location Name and/or Building Number Boiler Room		
Address 5363 Peru St			Boiler Location Address		
City Plattsburgh		State NY	Zip 12901	City	State 0
National Board # 140486	Jurisdiction # Asset 10089	Property # B-1	Boiler Use Closed Heating Loop		Fuel Type Electricity
Manufacturer Riverside Hydronics		Model # 126EWB125A-E		Serial # 1015140486	Year Built 2015
Capacity 430,000 BTU/HR	Design Pressure 150 psi	Operating Pressure 12-20 psi	Programmer Manufacturer Riverside Hydronics	Burner Manufacturer Electric elements	
Number of Safety Valves 1	Combustion Efficiency % CO2	ppm CO	% Excess O2	Flue Gas Temperature Degrees F	
Valve Manufacturer	Size	Set Pressure	Capacity	Lift Pressure	Reseat Pressure
Valve 1 Watts	3?4"	50 psi	1,352,000 BTU/HR	Hand	Sat
Valve 2					
Valve 3:					
Valve 4:					
Safety Devices Tested Cabinet Door Switch, Low Water Level Lockout, Operating Temperature Control, Upper Operating Thermostat, High Temperature Lockout, and Safety Relief Valve. Safety was lifted by hand per NBIC 2.5.7 e). It lifted freely and reseated with no leakage.					
Reason(s) for Declining Certification Both ASME CSD-1 CE-110 (b) and Part 1 Para. 3.5.3.1 c of the National Board Inspection Code require a remote emergency disconnect. This is a repeat finding from last years inspection.					
Comments This electric Hot Water Heating Boiler was inspected per UFC 3-430-07, ASME CSD-1, and the National Board Inspection Code. There was no evidence of leakage observed with system pressure of 15 psi on watersides of boiler. All safety devices tested functioned properly during the inspection process. Install plug/cap on ball valve installed on boiler drain to prevent personnel injury from accidental opening of valve.					
Inspector Commission 13373	Inspector Dale Brooks	Signature 			
Attachments Yes 1 Pages	Technical Manager Jerry Kuykendall	Signature 			