



CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

CUSTOMER PO. NO. CSS # 91584

**JOB NAME/LOCATION** USARC - New River Valley Memorial VA012  
**SERVICE REQUESTED** Room, NTE.

Manufacturer: Daikin  
Model#: RZQ18TAVJUA  
Serial#: E000245

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested
- Leak Found
- Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

set was hooked to the condenser. I fixed the leak and then pressurized the system again with nitrogen and did not find anymore leaks. Let the nitrogen out and then started pulling vacuum. I found i did not have enough freon so i left the unit on vacuum over night and told client i would be back first thing in the morning.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

JOB COMPLETE YES \_\_\_\_\_ NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**