

SERVICE REPORT

DATE 7-7-23ARRIVAL TIME 8:00DEPARTURE TIME 11:00

JOB/TCK. NO. 193741

CUSTOMER P.O. NO. CSS # 91584

JOB NAME/LOCATION *USARC - New River Valley Memorial VA012*

SERVICE REQUESTED (14) Investment is labor to leak check Daikin Split CU (M# RZQ18TAVJUA; S# E000245) that serves the Server

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

Manufacture: <u>Daikin</u>				
Model#: <u>RZQ18TAVJUA</u>				
Serial#: <u>E000245</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Set ladder up and took tools to the roof. Then checked the vacuum and system was pulled down to 350 microns. Took it off vacuum and then hooked gauges up. Then started charging the system up with R-410A. I put up 7 lbs in the system then reset the power and and waited for the unit to kick on. I went to the area where it was serving and turned the t-stat on. Went back to the roof and then checked and made sure everything was working properly. Put everything back together and then put tools away. Told client i was done.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO EXPLAIN

SIGNATURE _____

Customer Representative