

## Additional Funding Request

<b>NY126</b>	<b>CSS# 16697 WO# 8422 Asset# 7789</b>											
Description of Repairs	Labor and materials to replace defective cord reel on overhead door asset #7789											
Diagnosis: Initial Work Order	Additional work: Cord reel should be replaced it is functioning at this time but feel the connections are going to burn out inside the reel.											
Diagnostic Fee	\$0											
Additional Labor Cost to Perform Repairs	<p>\$ 320.00</p> <p>TW Labor \$80/hr x4</p>											
Additional Material Cost to Perform Repairs	<p>\$ 186.09</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">J2011 120664-005 Take Up Reel</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: right;">\$175.14</td> <td style="width: 10%; text-align: right;">\$175.14</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td style="text-align: right;">\$10.95</td> </tr> </table>				J2011 120664-005 Take Up Reel	1	\$175.14	\$175.14	Sales Tax			\$10.95
J2011 120664-005 Take Up Reel	1	\$175.14	\$175.14									
Sales Tax			\$10.95									
Total Cost of Repair	\$ 506.09											

