


Additional Funding Request

NY030 – Flag Pole Light	Maximo WO # 5768 CSS# 15335 Asset #NA
Description of Repairs	Labor and materials to install a new LED fixture and components for the flagpole lighting.
Diagnosis: Initial Work Order	Repair flag pole light. Conduit that light was mounted to is old and rusted the fixture itself is no longer attached to conduit now the Flag is not illuminated at night. Urgent request.
Explanation of Additional Costs for Repairs	Install new LED Fixture Replace Condulet Type T Replace photo Control \$300.00
Additional Labor Cost to Perform Repairs	\$92 an hour X 4 hours \$368
Total Cost of Repair	\$668.00



154 E. 5th St./P.O. Box 34, Elmira, N.Y. 14902-0034

Phone: (607) 734-6106
FAX (607) 733-5433

September 6, 2018

Tidewater Inc
6625-A Selnick Dr
Elkridge, MD 21075

Attn: Karlee Demain
RE: US Army Reserve Base Flagpole Light

Per your request, we present the following proposal to furnish and install a new LED fixture and components for the flagpole lighting, following site visit and inspection:

Scope of work:

- Install new LED fixture
- Replace conduit type T
- Replace photo control

Our price for the above described service including necessary labor and materials is \$668 (six hundred sixty eight dollars), plus applicable taxes. All work to be completed during normal business hours.

Labor: \$92/hr x 4 hr = \$368

Materials listed above: \$300

Total: \$668

Please feel free to contact us with questions or concerns.

Sincerely,
Bouille Electric, Inc.

Chris Dunbar