



Boiler #5 - The boiler shell is leaking. Repair the leak in accordance with manufacturer's recommendations, National Boiler Inspection Code and ASME Section IV.

Proposal is to remove and replace the Igniter, Pressure Gauge & 3' Drain hose.

CMI Cost Estimate								
Funding Request								
PA020 Dubois								
Boiler #5 The boiler shell is leaking.								
CSS #15936 - CMI # 5975								
Prepared By: J. Bayne								
12.10.18								
Asset #6583								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	3						\$ 294.00
1.2 Igniter kit, hose, pressure gauge					\$ -	\$ -	\$ -	\$ 227.12
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 545.12
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	3						\$ 294.00
Grand Total								\$ 839.12