



Boiler #4 - The wiring is not in accordance with the National Electric code. The wiring harness insulation is burned and deteriorated. Bare wires are exposed. Repair the wiring harness in accordance with the National Electrical Code.

Proposal to remove & replace worn igniter.

CMI Cost Estimate								
Funding Request								
PA020 Dubois								
Boiler #4 - The wiring is not in accordance with the National Electric code								
CSS #15935 - CMI # 5974								
Prepared By: J. Bayne								
12.10.18								
Asset #6583								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	1						\$ 98.00
1.2 Igniter					\$ -	\$ -	\$ -	\$ 149.74
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 271.74
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	1.5						\$ 147.00
Grand Total								\$ 418.74