



Found during PM Program.

Asset 3496 – Bathroom Exhaust Fan in 208 has been disconnected and is not working.

Proposal to provide and install new motor and capacitor & galvanized ductwork.

CMI Cost Estimate								
Funding Request								
PA042 Greensburg								
Bathroom Exhaust Fan not working								
CSS #15801 - CMI # 5936								
Prepared By: J. Bayne								
12.11.18								
Asset # 3496								
Description		Rate	Hours	Labor	Cost	Material	Sub	OHP
							Total	20%
1. Repair Cost								
1.1 Labor		\$ 98.00	4					\$ 392.00
1.2 Motor & Capacitor						\$ -	\$ -	\$ 143.36
1.3 Galvanized Ductwork								\$256.80
1.4 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 816.16
2. Initial Service Call Investigation								
2.1 Field Review at Site		\$ 98.00	1.5					\$ 147.00
Grand Total								