



Asset 6926, Push button Pendant, the mount for the hoist contact block is damaged inside the pendant, need to replace

Yale Crane 3865

Single girder EOT - 1 trolley wire rope hoist, 5 t, Bay Crane, EWRH 5.5t YALE sn W319100A mn CEW51/2X25RT18D3, BAY CRANE,

CMI Cost Estimate								
Funding Request								
PA051-227								
Push button Pendant, the mount for the hoist								
CSS #17015 - CMI # 5802								
Prepared By: J. Bayne								
1.03.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 112.00	4						\$ 448.00
1.2 Material					\$ -	\$ -	\$ -	\$ 300.00
1.3 Travel								\$291.20
Sub Total Repair Cost								\$ 1,039.20
2. Initial Service Call Investigation								
Grand Total								\$ 1,039.20