

Additional Funding Request

NY052 – Motion Sensor	Maximo WO # 7122 CSS# 16932 Asset #NA
Description of Repairs	Labor and materials to troubleshoot, repair/replace the following defective equipment (1) siren and (1) horn. NOTE: Lo current has previously worked on this system and did not need to conduct a site visit for this work. No pictures provided.
Diagnosis: Initial Work Order	Make repairs to broken motion sensor inside of vault. Troubleshoot and repair nonfunctioning alarm horn on exterior of facility. Note Physical Security inspection is 23 January 2019. Routine request
Explanation of Additional Costs for Repairs	Labor and material to troubleshoot the motion sensor inside the vault.
Investigative Diagnosis from SC	\$0 Subcontractor did not charge a diagnostic fee
Additional Material Cost to Perform Repairs	(1) Siren \$55.00 (1) Motion Sensor \$111.00
Additional Labor Cost to Perform Repairs	(\$125.00 an hour x 8 hours) = \$1000.00
Total Cost of Repair	\$1166.00