

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 5655</b>	<b>CSS # 21382</b>	<b>Asset# NA</b>
Description of Repairs	Repair Roof Leak Building 200		
Diagnosis: Initial Work Order <b>CSS# 21382</b>	Roof Leak Building 200		
Explanation of Additional Costs for Repairs	Labor and material to temp stop the leak		
Additional Labor Cost to Perform Repairs	$6 \times \$190 = \$1140.00$		
Additional Material Cost to Perform Repairs	\$350.00		
Total Cost of Repair	\$1490.00		

# ACAV SERVICES

September 17, 2019



ESTIMATE 0917191 CSS2182

Bill To		Ship To	
Customer	International Support Group J Merchant, M Merchan	Recipient	99 RSC DPW R Linn
Customer ID#	NY023	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	718 790 3562		
Payment Due	NET 30	Delivery Date	September 25, 2019
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p><b>Building 200 Ft Totten</b></p> <p><b>Room 3009B Possible Roof Leak</b></p> <p><b>Inspected Roof and Ceiling possible</b></p> <p><b>Roof failure is causing water to gather</b></p> <p><b>under the foam insulation on the</b></p> <p><b>rubber roof, Roof might need</b></p> <p><b>replacement.</b></p> <p><b>Recommend trying to temporally stop</b></p> <p><b>the leaks by applying a rubber</b></p> <p><b>waterproofing material to the areas in</b></p> <p><b>question inside the upper ceiling.</b></p> <p><b>Replace damaged ceiling tile.</b></p> <p><b>Material</b></p> <p><b>Labor 6 hrs x \$190.00</b></p> <p><b>TOTAL</b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NP623 Blag 20 Date of Visit: 9/17/19

Contractor Personnel on Site:

1. Taylor 2. \_\_\_\_\_

Work Performed: Room 3009B CSS# 2152

**Preventive Maintenance** -(Annual, Quarterly, Monthly, equipment identification, etc.)  
**Service Orders** -

Asset #	Qty	Asset Description
		Room 3009 B
		POSSIBLE Roof Coats Under Forn
		NO VISIBLE Paper Lining
		SEAL Frame and other Areas

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Troy Ahe Date: 8/07/18  
Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Louis Corbo Date: \_\_\_\_\_

Signed: Louis Corbo

E-Mail: Louis.A.Corbo-ctr@mail.mil

LSS # 21382

Room 3009 B



CS34 21382 Room 3009B

