

Additional Funding Request

| NY024 | CSS #15938 | WO3390 | ASSET #9767 |
|---|--|--------|-------------|
| Description of Repairs | Take CL apart and adjust and lubricate. Dig out area around wheels and perform basic maintenance. Put CL back together | | |
| Diagnosis: Initial Work Order | the gate lower rollers have slid down causing the gate to hit the ground. | | |
| Explanation of Additional Costs for Repairs | N/A | | |
| Additional Labor Cost to Perform Repairs | \$ 675.00 | | |
| Additional Material Cost to Perform Repairs | \$0.00 | | |
| Shipping | N/A | | |
| Total Cost of Repair | \$675.00 | | |
| | | | |