

Additional Funding Request

NYNY116	CSS # 18954	WO4094	ASSET #
Description of Repairs	Replace fan motor in cooling air handler for 2 nd floor area. Install new motor, wire to control center.		
Diagnosis: Initial Work Order	replace AH 8J fan motor this unit cools 2nd floor		
Explanation of Additional Costs for Repairs	N/A		
Additional Labor Cost to Perform Repairs	\$ 400.00 (4MH @ \$100.00/MH)		
Additional Material Cost to Perform Repairs	\$362.00		
Shipping	N/A		
Total Cost of Repair	\$762.00		