

Wo 7158 - CSS 17023- PA166- Emergency- Troubleshoot and repair 2 S-Flex drives. Fuses were blown and replaced. Upon starting the drive with new fuses, the drive failed to operate again. Further investigation finds that a contactor in each drive has failed. Schneider Electric LADN20 and LAD4RC3U.