

## Additional Funding Request

Submitted: 4/22/21

<b>MD066 – Louvers are not open</b>	<b>CSS #29391 WO# 13859</b>												
Description of Repairs	S&S was onsite and found that the damper motor in the unit had no response. S&S proposes to remove and replace the damper motor. S&S will then complete a system check to ensure the system is running correctly. Previous investigation in the total of \$700.00 from quote 547, further labor was needed to troubleshoot with TMI												
Original SC Investigative Diagnosis	<b>\$700</b>												
Diagnosis: Initial Work Order	Unit is running but louvers are not open. BLDG EMS has fan in alarm. Location is in the storage/cage area of bldg.1. Back near the offices.												
Explanation of Additional Costs for Repairs	N/A												
Additional Material Cost to Perform Repairs	<p><b>Materials: \$283.34</b></p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>GMA221.1U 2PT SR, 120V, 62LBIN Motor</td><td>1</td><td>\$233.34</td><td>\$233.34</td></tr> <tr> <td>Shipping</td><td>1</td><td>\$50.00</td><td>\$50.00</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	GMA221.1U 2PT SR, 120V, 62LBIN Motor	1	\$233.34	\$233.34	Shipping	1	\$50.00	\$50.00
ITEM	QUANTITY	UNIT PRICE	TOTAL										
GMA221.1U 2PT SR, 120V, 62LBIN Motor	1	\$233.34	\$233.34										
Shipping	1	\$50.00	\$50.00										
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$900.00</b> HVAC Labor/9 hours/Rate \$100.00 per hour = \$900.00</p>												
<b>CM CREDIT</b>	<b>(<span style="color: red;">\$250.00</span>)</b>												
<b>Total Cost of Repair</b>	<b>\$1633.34</b>												