

-----Original Message-----

From: Bacani, Paul D CIV USARMY CENAP (US) <Paul.D.Bacani@usace.army.mil>  
Sent: Tuesday, August 20, 2019 10:43 AM  
To: Steve Miller <steve.miller@cmimgmt.com>  
Cc: Bowling, Mark J CW3 USARMY 99 RD (USA) <mark.j.bowling4.mil@mail.mil>; Boyle, Peter J CIV USARMY 99 RSC (US) <peter.j.boyle1.civ@mail.mil>  
Subject: FW: 99TH FIS R2 ACTION REQUIRED - FAC ID NY116 - IDIQ 18746 - CMI WO 5467 -  
Stacked Service Call Over \$2500

Steve. The contracting officer has approved the following additional work to proceed:

Site NY116  
CSS # 18746  
CMI WO # 5467  
Asset # NA

Scope: Perform the following repairs and/or replacements:

1. Replace Batteries in Stand Alone Emergency Lighting Wall Packs for egress lighting in AMSA Building & Administration Building.
2. Replace Faulty Emergency Lighting for egress lighting in AMSA building & Administration Building.

Labor Cost	\$2,800.00
Equipment cost is	\$2,958.00
Total Cost	\$5,182.20

VR

Paul D. Bacani, AIA, BOCA, RCS  
Project Engineer  
Contracting Officer Representative  
U.S. ARMY CORPS OF ENGINEERS-PHILADELPHIA DISTRICT Construction Branch Central NJ  
Resident Engineer Office U.S. Army Corps of Engineers  
Tel: (609) 562-2925  
Mobile: (609) 508-0037  
E-Mail: paul.d.bacani@usace.army.mil