

The Genuine. The Original.



INVOICE

Invoice # 307711

Date: 06/25/19

Bill To:
**CMI MANAGEMENT
PRODUCTION CONTROL
5285 SHAWNEE ROAD, SUITE 510
ALEXANDRIA, WV 22312**

Ship To:
**USARC - WASHINGTON
10 SCENIC DRIVE
WASHINGTON, PA 15301**

Customer PO #	Customer Phone	Sales Representative	* Terms	Factory Ack.	Job #
CSS16635		SERVICE	UPON RECEIPT	CMI/ARM	10377

Description	Total
2/1 - LABOR AND MATERIAL TO RELEASE JAMMED DOOR, ADJUST INTERLOCK SWITCH, RE-ALIGN AND TIGHTEN DRIVE CHAIN SPROCKET, ADJUST LIMITS AND LUBRICATE DOOR.	959.59
LABOR - 8.5 MAN HOURS @ 98.00 = \$833.00	
MATERIAL - 126.59	
Invoice subtotal	959.59
Invoice total	959.59

*NOTE: Late payments shall incur an additional charge of 1-1/2% interest
per month or fraction thereof.


959.59

Bal. Due

Thank You

OVERHEAD DOOR COMPANY OF GREATER PITTSBURGH - 400 POPLAR STREET - PITTSBURGH, PA 15223
PHONE 412-781-4000 FAX 412-781-2446

The Genuine. The Original.



"OVERHEAD DOOR"
SCISSOR LIFT OR
FORK LIFT USED:

NONE (X)
 ONE () BOTH ()

DESCRIPTION OF WORK PERFORMED 1st CALL

* TRAVEL SHOT DOOR / OPERATOR AND FOUND INTERLOCK
SWITCH STICKING, SPROCKET OUT OF ALIGNMENT (LOOSE),
PNEUMATIC EDGE BAD, AND MANUAL HOIST NOT WORKING
* ADJUSTED : ADD. INTERLOCK SWITCH
* PLACED : TIGHTENED SPROCKET (DEVI CROWN)
* PLACED MISSING SET SCREW ? ADD. HOIST TO FLOOR.
* ADD. LEADS, USED DOOR TALK INTO, 3 TIRE ROLL
JOB
COMPLETED YES() NO() ACCEPTED
BY: *Shane Fabian*

DESCRIPTION OF WORK PERFORMED 2nd CALL

* REVERSED AND BROKE PNEUMATIC HOSE
* INSTALLED NEW PNEUMATIC HOSE AND RECONNECTED
HOSE (STILL LEAKS)
* TIRE ROLL

JOB
COMPLETED YES() NO() ACCEPTED
BY: *Shane Fabian*

DESCRIPTION OF WORK PERFORMED 3rd CALL

NATURE OF CALL:

Drill Hall Door

Door inoperable.

When pushing the open/close button, the motor
is not engaging. *Stack*

2nd CALL. REPLACE PNEUMATIC BOX & HOSE.

* MUST TAKE BEFORE AND AFTER PICTURES

* GET PHOTO OF ASSET NUMBER

* GET ATTACHED SHEET SIGNED.

****After 1 hour of service, please call the office for
amount.

Upon inspection our service technician recommends:

* REPLACE PNEUMATIC EDGE BOX & HOSE

JOB
COMPLETED YES() NO() ACCEPTED
BY:

* NO SAFETY ENTRAPMENT DEVICE *

WORKING - UNTIL REPAIRS ARE MADE

QUANTITY MATERIAL DESCRIPTION AMOUNT

1	SET SCREW	
1	135	LUG
1		PNEUMATIC BOX

Recommendations approved by:

Email quote to:

Recommendations NOT approved by:

PRINT NAME: *Hannan J. Hall*

Date: *2/1/19*

	1st CALL	2nd CALL	3rd CALL	AMOUNT
DATE	<i>2/1/19</i>	<i>2/27/19</i>		TOTAL MATERIAL
IN	<i>1130</i>	<i>1400</i>		SERVICE CHARGE
OUT	<i>1430</i>	<i>1509</i>		LABOR
TRAVEL	<i>35 min</i>	<i>9 min</i>		OVERTIME
MECH	<i>Ken</i>	<i>Ken</i>		TOTAL DUE
MECH	<i>Fisher</i>	<i>Fisher</i>		



Management, 155: Overhead door located in drill hall is inoperable. When pushing the open/close button on switch, the motor fails to engage. No breakers were tripped. Request is for vendor to troubleshoot and repair.

*Repairs already made – received Verbal Approval from David L.


Labor and material for the following:


- *Release jammed door
- *Adjust interlock switch
- *Re-align and tighten drive chain sprocket
- *Secure and adjust chain hoist
- *Adjust limits and lubricate door.


CSS# 16635


Recommended Work:


*Install new Pneumatic edge box with hose.











PA096-01

Asset # 7721-Door,Ovhd-

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA 096

Date of Visit: 2/19

Contractor Personnel on Site:

1. <u>Ken Kuestick, Jr.</u>	4. _____
2. <u>Fisher Stewert</u>	5. _____
3. _____	6. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____

Inspection, Testing, and Certification

1. _____
2. _____
3. _____
4. _____

Other Recurring Services

1. _____
2. _____
3. _____
4. _____

Service Calls - Service Call Number and Description

1. <u>10377 - Dore INOPERABLE</u>
2. _____
3. _____

Over and Above Repair Work – Order Number and Description of Work Completed

10377 - DUE TO IMPERFECT; FOUND INTERLOCK SWITCHING, DRIVE SPACER
OUT OF ALIGNMENT, SAFETY EDGE BAD, AND MANUAL HOIST NOT WORKING
- DISASSEMBLED & ADJ. INTERLOCK SWITCH
- REASSEMBLED DRIVE SPACER
- REPLACED MISCELLANEOUS SET SCREWS & ADJ. HOIST TO WORK
- ADJ. WHEELS, LUBED DOOR, TALK TO RD, AND TEST RAN

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: KENNETH K. KURSTRECK, JR. Date: 2/1/19

Signed: Kenneth K. Kurstreck Jr.

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Hannah L. Florian GS-C9 Date: 20190201

Signed: Hannah L. Florian

E-Mail: hannah.l.florian.civ@mail.mil