



Asset-3912 EF-2 Has a seized bearing and is inoperable and the motor or the entire exhaust fan will need to be replaced before it will function.

Asset-3506 EF Has a seized bearing in the motor and is inoperable and the motor or the entire exhaust fan will need to be replaced before it will function.