

Additional Funding Request

NY067	CSS# 11 WO# 17189 Asset# NA
Description of Repairs	Labor and materials to replace X10 Lock
Diagnosis: Initial Work Order	Arms vault lock mechanism is worn and needs to be repaired
Diagnostic Fee	\$ 0
Additional Labor Cost to Perform Repairs	\$ 225 TickTock Labor (see attached)
Additional Material Cost to Perform Repairs	\$ 639
Total Cost of Repair	\$ 864

Tick Tock Safe and Lock

PO Box 311
Liverpool, NY 13088
(315) 944-0532
service@ticktocksafeandlock.com
http://www.ticktocksafeandlock.com



Estimate

ADDRESS

Tidewater Inc.
3761 Attucks Dr
Powell, OH 43065

ESTIMATE # 220419-01**DATE** 04/19/2022**EXPIRATION DATE** 06/17/2022**WORK ORDER/PO NUMBER**

NY067 Army Reserve Vault Lock

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	S&G 2937 Safe Lock Complete	1	639.00	639.00T
	Travel	1	75.00	75.00T
	Install X10/2740 Lock	1	150.00	150.00T
			SUBTOTAL	864.00
			TAX	0.00
			TOTAL	\$864.00


Accepted By

Accepted Date

YOU ARE NOT LOCKED IN

1. To unlock door, use key on hook to unlock lock (turn key counterclockwise).
2. Operate door handle to open door (located below).
3. To relock, with the door open, throw bolts to locked position. Relock the key lock and replace key on hook.
4. To close and lock door, dial combination lock open, throw bolts to unlocked position, close door and throw bolts to locked position and scramble combination lock.

* This procedure is a security safeguard requiring knowledge of combination to close and relock door after emergency release has been activated.



CAUTION

PLACE CHANGE KEY
HERE TO BE SURE
IT IS CORRECT ONE

DO NOT USE
IF KEY DOES NOT
MATCH PATTERN

FOR ALL THREE WHEEL LOCKS
AND NEW-STYLE MP LOCKS



SARGENT &
GREENLEAF, INC.



