

Additional Funding Request

MD019	CSS# 15569 WO# 9625 Asset# 2047							
Description of Repairs	Labor and Materials to do a Leak Test on the refrigerant circuit #1. Will then open the valves to let nitrogen into the evaporator barrel to confirm this is the common point for both circuits.							
Diagnosis: Initial Work Order	Additional work needed to charge system and pin point where the refrigerant leak is.							
Diagnostic Fee	\$0							
Additional Labor Cost to Perform Repairs	\$ 570 SS Mechanical Labor \$95/hr x 6							
Additional Material Cost to Perform Repairs	<div>\$388.22</div> <table><tr><td>Nitrogen R31 255 CU FT grade 4.5 High Purity (includes tax)</td><td>1</td><td>\$388.22</td><td>\$388.22</td></tr></table>				Nitrogen R31 255 CU FT grade 4.5 High Purity (includes tax)	1	\$388.22	\$388.22
Nitrogen R31 255 CU FT grade 4.5 High Purity (includes tax)	1	\$388.22	\$388.22					
Total Cost of Repair	\$ 958.22							

NOTE: Rick Hicks will be on site at no additional charge to oversee.





