

Additional Funding Request

should be WO 6840 rather than 6480

DE007	CSS# 16326 WO# 6480 Asset# NA								
Description of Repairs	Labor and materials to replace bad glycol pump.								
Diagnosis: Initial Work Order	Once glycol was delivered onsite, it was found that the pump was leaking and requires replacement.								
Diagnostic Fee	\$0								
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>TW Labor \$80/hr x 6</p>								
Additional Material Cost to Perform Repairs	<p>\$1,366.20</p> <table border="1"> <tr> <td>120/240VAC Enclosed Fancooled Pump - 6NZL6</td> <td>1</td> <td>\$1,296.00</td> <td>\$1,296.00</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$70.20</td> </tr> </table>	120/240VAC Enclosed Fancooled Pump - 6NZL6	1	\$1,296.00	\$1,296.00	Sales Tax			\$70.20
120/240VAC Enclosed Fancooled Pump - 6NZL6	1	\$1,296.00	\$1,296.00						
Sales Tax			\$70.20						
Total Cost of Repair	\$ 1,846.20								



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	DE007
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Mech Room
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace bad glycol pump.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
120/240VAC Enclosed Fancooled Pump - 6NZL6	1	\$1,296.00		\$1,296.00
Sales Tax				\$70.20
SUB-TOTAL COSTS:		Materials Total	\$1,366.20	Labor \$480.00
		TOTAL		\$1,846.20

GOULDS WATER TECHNOLOGY

120/240VAC Totally Enclosed Fan-Cooled Straight Center Discharge Pump, 1-Phase, 1-1/4" NPT Inlet Siz

Item # **6NZL6** Mfr. Model # **1ST1C4E4** Catalog Page # **2635** UNSPSC # **40151503**



Web Price i
\$1,080.00 / each

One Time Delivery

1

+ Add to List

Shipping

Pickup

Expected to arrive **Mon. Dec 10.**

Ship To **43065** (Change)

Jump to:

Replacement Parts

★ ★ ★ ★ ★ [Be the first to write a review](#)

Shipping Weight **39.4 lbs.**

[How can we improve our Product Images?](#)

[Compare](#)

Country of Origin **USA** | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.
[More](#)

EMERSON™

MODEL C55JXJZC-4758
VOLTS 115/208-230
HP 1/2 RPM 3450
AMPS 8.2/4.2-4.1
SF AMPS 10.8/5.9-5.4
HP RPM 220-230
VOLTS 4.9-5.2
AMPS 2850
THERMALLY PROTECTED AUTO

ST. LOUIS, MO. U.S.A.
MADE IN MEXICO

SF 1.6/1.0
HZ 60/50
DUTY CONT
INS CLASS B

AMB 50°C
MFG NO E10C

CODE M
FRAME

®

SP

156060

CE IP22
WARNING :

COMPONENT COVER
ELECTRICAL SHOCK
PROT. CODE 04420

MOTOR MUST BE GROUNDED IN ACCORDANCE
WITH LOCAL AND NATIONAL ELECTRIC CODES.
COVER MUST BE IN PLACE BEFORE OPERATING TO PREVENT
INJURY.

JZC-4758

CUSTOMER NO
E04853S

LOW VOLTAGE
LINE
BLK 20
BRN 10
3
WHT 4
P
HIGH VOLTAGE
LINE
BLK 10
WHT 3
BRN 4
NEUTRAL

TESTED OK
PUMP MADE WITH
QUALITY AND
PRIDE IN USA
J.
SANDRONI

REVISED
INSTRUCTIONS FOR
CONNECTIONS FOR
230 VOLTS
MAY DRY
OUT
OVER
TIME
CAUTION