

Additional Funding Request

DE001	CSS# 16568 WO# 6833 Asset# NA											
Description of Repairs	Labor and materials to replace exterior wall pack light that was hit by vehicle.											
Diagnosis: Initial Work Order	One of the exterior lights on the OMS building has come detached from the building and is hanging by the power wiring. Looks like the mount came loose from the brick. Need to have light remounted and make sure that it is working properly.											
Diagnostic Fee	\$240 TW Labor 3 hours @ \$80/hr											
Additional Labor Cost to Perform Repairs	\$240 TW Labor 3 hours @ \$80/hr											
Additional Material Cost to Perform Repairs	<p>\$504.74</p> <table border="1"> <tr> <td>60W Bronze Wallpack - FL2F28022</td> <td>1</td> <td>\$478.80</td> <td>\$478.80</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$25.94</td> </tr> </table>				60W Bronze Wallpack - FL2F28022	1	\$478.80	\$478.80	Sales Tax			\$25.94
60W Bronze Wallpack - FL2F28022	1	\$478.80	\$478.80									
Sales Tax			\$25.94									
Total Cost of Repair	\$ 984.74											



WORK ESTIMATE

CSS #:

16568

Work Order #:

6833

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	DE001
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	OMS Building Exterior
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace exterior wall pack light that was hit by vehicle.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			3	\$240.00
60W Bronze Wallpack - FL2F28022	1	\$478.80		\$478.80
Sales Tax				\$25.94
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:		Materials Total	\$504.74	Labor \$480.00
		TOTAL		\$984.74

Adam Colopy

From: Adam Colopy
Sent: Wednesday, January 23, 2019 9:35 AM
To: Adam Colopy
Subject: RE: Dover reserve center light replacement

From: Mike Drew Jr. <mdrewjr@drewinvestmentgroup.com>

Date: January 23, 2019 at 08:06:01 EST

To: John Brown <john.brown@tideh2o.net>

Subject: Re: Dover reserve center light replacement

Yes sir. The base price for a 60W Bronze wallpack is 399.00. And again that will come with a 10year full replacement warranty, excluding hits from fork lifts obviously hah.

Michael C Drew Jr.

Project Management

Drew Investment Group

2035 Barnhill Orchard Rd.

Morganton, NC 28655

mdrewjr@drewinvestmentgroup.com

Cell: 843-469-9146

Office: 888-943-3052

MODEL: FL2F28022 FILE: E340511
INPUT: 120-277V~ 50/60Hz, Max. 0.55A, 60W
THIS PRODUCT MUST BE INSTALLED IN ACCORDANCE
WITH THE APPLICABLE INSTALLATION CODE BY
A PERSON FAMILIAR WITH THE CONSTRUCTION AND
OPERATION OF THE PRODUCT AND THE HAZARDS
INVOLVED. CAUTION - RISK OF SHOCK. DISCONNECT
POWER BEFORE SERVICING. SUITABLE FOR OPERATION IN
AMBIENT NOT EXCEEDING 40°C. SUITABLE FOR WET LOCATION

