

Additional Funding Request

NY070	CSS# 16944 WO# 7160 Asset# NA								
Description of Repairs	Labor and materials to temperature control knob thermostat on parts washer.								
Diagnosis: Initial Work Order	Make repairs to temperature control knob on parts washer. The dial is broken off and the rod that adjust the temperature is not functioning.								
Diagnostic Costs	\$ 320 TW Labor 4 Hours @ \$80/Hr								
Additional Labor Cost to Perform Repairs	\$ 160 TW Labor 2 Hours @ \$80/Hr								
Additional Material Cost to Perform Repairs	\$ 180.25 <table border="1" style="margin-left: 20px;"> <tr> <td>Thermostat Control Knob, PECO - TB125-031</td> <td>1</td> <td>\$168.00</td> <td>\$168.00</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$12.25</td> </tr> </table>	Thermostat Control Knob, PECO - TB125-031	1	\$168.00	\$168.00	Sales Tax			\$12.25
Thermostat Control Knob, PECO - TB125-031	1	\$168.00	\$168.00						
Sales Tax			\$12.25						
Total Cost of Repair	\$ 660.25								



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	NY070
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Maintenance Bay
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to temperature control knob thermostat on parts washer.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			2	\$160.00
Thermostate Contorl Knob, PECO - TB125-031	1	\$168.00		\$168.00
Sales Tax				\$12.25
Diagnostic Labor			4	\$320.00
SUB-TOTAL COSTS:		Materials Total	\$180.25	Labor \$480.00
		TOTAL		\$660.25

PUMP

OFF



INTERMATIC

HEAT



WA
MU
FRE
REV



TB125-031 PECO. INC.

**CRK[®]
c CRK US**

E50023

220F

0841R

MADE IN CHINA