

## Additional Funding Request

<b>MD019</b>	<b>CSS# 17442 WO# 7268 Asset# 2061</b>			
Description of Repairs	Replace Safety Edge on overhead garage door.			
Diagnosis: Initial Work Order	Labor and materials to replace safety edge on overhead garage door.			
Diagnostic Fee	\$0			
Additional Labor Cost to Perform Repairs	\$ 400.00 TW Labor \$80/hours x5			
Additional Material Cost to Perform Repairs	\$ 777.23			
	20'0" Miller edge 4 wire monitored safety edge with mounting Channel	1	735.84	\$735.84
	Sales Tax			\$41.39
PM Credit	<b>-\$250.00</b>			
Total Cost of Repair	\$ 927.23			



# WORK ESTIMATE

CSS #: 17442

Work Order #: 7268

Emergency ☐ Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	MD019
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	John Brown		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace Safety Edge on garage door asset #2061

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			5	\$400.00
20'0" Miller edge 4 wire monitored safety edge with mounting Channel	1	\$735.84		\$735.84
Sales Tax				\$41.39
SUB-TOTAL COSTS:	Materials Total	\$777.23	Labor	\$400.00
TOTAL			\$1,177.23	

Shop by Category

Shop by Brand

On Sale

Product Info

1

SHIPPING

2

PAYMENT

3

CONFIRMATION

Questions? Call us at 440-365-5707 Mon-Fri 8:00am - 5:00pm Eastern Time.

## SHOPPING CART

ITEM

OPTIONS

UNIT PRICE

QTY.

COST



MillerEdge Pressure Sensitive Sensing Edge ME123 - Sold by the Foot

Configuration : Non-Monitored  
Outlet Location : Left  
Color : Black  
Mounting Channel : ME123-C7

\$30.66

20

\$613.20

Subtotal: \$613.20

Shipping: \$3.66

Tax: \$41.39

Total: \$658.25



