

Additional Funding Request

Submitted: 08/09/2022

NY067	CSS 1884 WO 18964			
Description of Repairs	Labor and materials to replace the key box with a new key box, mounting it on the wall where the old key box was.			
Original SC Investigative Diagnosis	\$160			
Diagnosis: Initial Work Order	Repair Facility key box			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$ 587.88			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Materials (See attached detail)	1	587.88	587.88
Additional Labor Cost to Perform Repairs	Labor: \$240 TW Labor \$80/ hr x 3			
Total Cost of Repair	\$987.88			



Customer Quotation

To:

TIDEWATER INC
6625 SELNICK DR #A
ELKRIDGE MD 21075-6220

Information

Date	08/05/2022
Customer Account Number	885295220
Grainger Quote Number	47093281
Customer Job Number	
Contract Number	
Grainger Representative	John R Romano
Phone Number	
Fax Number	
Email	
Grainger Tax ID	36-1150280

Item	Description Manufacturer Name & Model	Cat. Pg. #	Qty	\$ Quote	Ext. Price	Start Date	Exp. Date
53JF29	Key Cabinet,400 Capacity,21-3/4" H BARSKA CB12490 Country of Origin: China		1	489.90	489.90	08/05/2022	12/31/2022
				Total \$	489.90		

All orders are subject to the terms and conditions in your current contract with Grainger or to Grainger's current Terms of Sale as set forth on Grainger.com

Thank You!
Visit us at grainger.com

