



John A. Sullivan
Electrical Contractor Inc.
1 Pepe Road
Boonton, New Jersey 07005
973-334-0291 Fax 973-299-9398 N. J. Electrical License 7785A
Email jasullivanelect@gmail.com

CMI Management Inc.
Attn. Steve Miller
5285 Shawnee Road
Alexandria, VA. 22312

Quotation for Electrical Work Repairs of HVAC Motor

For: **New Windsor USARC** 6/10/2019
Location: New Windsor , N.Y.

Scope of work involved at New Windsor USARC

CSS18954 WO# 4094

1. Replace fan motor in cooling air handler for 2nd floor area. Install new motor, wire to control center.

Labor Rate \$ 100.00 per hour x 4 Hours \$ 400.00

Fan Motor \$ 310.00

Materials	\$310.00
Labor	400.00
Mark-Up 20%	<u>\$62.00</u>
TOTAL	\$772.00

Additional Funding Request

NYNY116	CSS # 18954	WO4094	ASSET #
Description of Repairs	Replace fan motor in cooling air handler for 2 nd floor area. Install new motor, wire to control center.		
Diagnosis: Initial Work Order	replace AH 8J fan motor this unit cools 2nd floor		
Explanation of Additional Costs for Repairs	N/A		
Additional Labor Cost to Perform Repairs	\$ 400.00 (4MH @ \$100.00/MH)		
Additional Material Cost to Perform Repairs	\$362.00		
Shipping	N/A		
Total Cost of Repair	\$762.00		