

Additional Funding Request

DE001	CSS# 19755 WO# 9584 Asset# 1703											
Description of Repairs	Labor and materials to remove and replace the thermistor on the Fujitsu mini-split.											
Diagnosis: Initial Work Order	The two mini-split units in the offices of the shop building are not working properly. One of these offices houses the servers for the shop and I have concerns over heat damaging the servers if they are not repaired (reason for the urgent priority)											
Diagnostic Fee	\$ 450											
Additional Labor Cost to Perform Repairs	<p>\$ 855</p> <p>SS Mechanical Labor \$95/hr 9</p>											
Additional Material Cost to Perform Repairs	<p>\$45.24</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">10 in. Adjustable Metal Worm Duct Clamps (2-Pack) Sales tax included</td> <td style="width: 10%;">1</td> <td style="width: 10%;">\$45.24</td> <td style="width: 10%;">\$45.24</td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </table>				10 in. Adjustable Metal Worm Duct Clamps (2-Pack) Sales tax included	1	\$45.24	\$45.24				
10 in. Adjustable Metal Worm Duct Clamps (2-Pack) Sales tax included	1	\$45.24	\$45.24									
Total Cost of Repair	\$ 1,350.24											



S&S MECHANICAL

S&S Mechanical

Location: Fleming-Godwin USARC
344 North New Street
Dover, DE 19904

Proposal Submitted to: Adam Colopy

Project: DE001 WO# 9584

Office # 301-574-1555

Fax # 301-574-1558

seth@sandsmidatlantic.com
sandsmidatlantic.com

S&S proposes to come out and remove and replace the thermistor on the Fijitsu mini-split:

Diagnostic Total: \$450.00

Materials: \$45.24

Thermistor QTY 2 /k9900965013/ \$45.24

Labor: \$855.00

1 HVAC Technician/9 Hours/\$95.00 rate=\$855.00

Full estimated total: \$1,350.24

Payments to be made as follows: 15 days upon approved invoice

Respectfully submitted: Brian Davis/Lindsay Ruby Dated: 06/28/19



JOHNSTONE SUPPLY THE BALSAN GROUP

JOHNSTONE ANNAPOLIS
1981 MORELAND PKWY, SUITE 101
ANNAPOLIS, MD 21401
Phone 410-280-0101
Fax 410-280-0104

SOLD TO:

SHIP TO:

Acknowledgement

ORDER DATE	ORDER NUMBER
06/28/2019	100-100694476
JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 Phone 410-280-0101 Fax 410-280-0104	PAGE NO. 1 of 1

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

REFRIGERANT R410A

CAUTION

- R410A refrigerant is charged in this Air-Conditioner.
- By additional charging, do not mix other refrigerant.
- Connecting the pipes, vacuuming and additional charging shall be done correctly as instructed in the installation manual.

CAUTION: MOVING PARTS.
DO NOT OPERATE UNIT WITH
CABINET REMOVED.

WARNING: RISK OF ELECTRIC SHOCK.
CAN CAUSE INJURY OR DEATH.
DISCONNECT ALL REMOTE ELECTRIC
POWER SUPPLIES BEFORE SERVICING.

AVERTISSEMENT: RISQUE DE CHOCS
ÉLECTRIQUES. PEUT CAUSER DES
BLESSURES ET MÊME ENTRAINER
LA MORT. COUPER LES SOURCES
D'ALIMENTATION À DISTANCE
AVANT LE DÉPANNAGE.

FUJITSU

SPLIT TYPE AIR CONDITIONER

OUTDOOR USE

MODEL No. AOU18RLXFZ

SERIAL No. LTN 021536

AHRI CERTIFIED

www.ahri.org/cert

Energy Star
www.energystar.gov

ENERGY STAR
www.energystar.gov