

## Additional Funding Request

<b>NY035</b>	<b>CSS# 20688 WO# 5106 Asset# 9886</b>																			
Description of Repairs	Labor and materials needed to replace faulty push button station and wiring for the Overhead door Asset 9886																			
Diagnosis: Initial Work Order	Repair the Push Button Station on Asset #9886																			
Diagnostic Fee	<p>\$ 160</p> <p>TW Labor \$80/hr x 2</p>																			
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>TW Labor \$80/hr x 6</p>																			
Additional Cost	<p>\$ 324.33</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Cable 100 FT, Conductors: 4C2425A #26121629</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">\$244.94</td> <td style="padding: 2px; text-align: right;">\$244.94</td> </tr> <tr> <td style="padding: 2px;">3 Button Controller PBS-3 #30171512</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">57.35</td> <td style="padding: 2px; text-align: right;">\$57.35</td> </tr> <tr> <td style="padding: 2px;">Sales Tax</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px;"></td> <td style="padding: 2px; text-align: right;">\$22.04</td> </tr> <tr> <td style="padding: 2px;"><b>CM CREDIT</b></td> <td style="padding: 2px; text-align: center;"><b>1</b></td> <td style="padding: 2px; text-align: right;"><b>-250.00</b></td> <td style="padding: 2px; text-align: right;"><b>-250.00</b></td> </tr> </table>				Cable 100 FT, Conductors: 4C2425A #26121629	1	\$244.94	\$244.94	3 Button Controller PBS-3 #30171512	1	57.35	\$57.35	Sales Tax	1		\$22.04	<b>CM CREDIT</b>	<b>1</b>	<b>-250.00</b>	<b>-250.00</b>
Cable 100 FT, Conductors: 4C2425A #26121629	1	\$244.94	\$244.94																	
3 Button Controller PBS-3 #30171512	1	57.35	\$57.35																	
Sales Tax	1		\$22.04																	
<b>CM CREDIT</b>	<b>1</b>	<b>-250.00</b>	<b>-250.00</b>																	
Total Cost of Repair	\$ 714.33																			



# WORK ESTIMATE

CSS #:  Work Order #:   
Emergency  Urgent  U-CM  Routine  X

Company Name:	Tidewater, Inc.	Facility ID:	NY035
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>	Classroom/Room #)	
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT				
Labor and materials to replace faulty push button station and wiring of the Overhead Door. Asset #9886				

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Communication Cable 100 FT, Conductors: 4C2425A #26121629	1	\$244.94		\$244.94
3 Button Controller PBS-3 #30171512	1	\$57.35		\$57.35
Sales Tax				\$22.04
Diagnostic			2	\$160.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$324.33</b>	<b>Labor</b> \$640.00
		<b>TOTAL</b>		<b>\$964.33</b>



# Cart

Item	Quantity	Total Price	Item Availability
 <b>CAROL</b> Unshielded Communication Cable, 100 ft. Length, Gray Jacket Color, Conductors: 4 (0 Pair) Item #20KZ85 Your Price: \$204.12	1	\$204.12	Expected to arrive <b>Mon. Aug 19</b> using standard ground shipping (additional shipping options available at Checkout.)
 <b>TELECTRON</b> 3 Button Control Station Item #6X891 Your Price: \$47.79	1	\$47.79	Expected to arrive <b>Mon. Aug 19</b> using standard ground shipping (additional shipping options available at Checkout.)

 Chat with an Agent

DOOR MAY FAIL IF OPERATED  
ELECTRICALLY IF OBSTRUCTED!  
**CAUTION:**  
DO NOT REMOVE ANY OBJECT THAT BECOMES STUCK DUE TO  
OPERATION OF THE DOOR. SERIOUS INJURY MAY RESULT!  
CONTACT AN AUTHORIZED DOOR SERVICE COMPANY.  
SEE DECAL AT BOTTOM CENTER OF DOOR AND ON WALL NEAR DOOR CONTROL.  
PN 49-45 TO REORDER (510) 467-2501

