

## Additional Funding Request

<b>MD002</b>	<b>CSS# 21680 WO# 11082 Asset# NA</b>																			
Description of Repairs	Labor and materials to replace repair gang cover plate in vestibule and door handle assembly for rooms 117 and 118. Also to repair (2) door stops on the doors at top of lobby stairs.																			
Diagnosis: Initial Work Order	Repair single gang cover plate in vestibule, and door handle assembly (inlc interior of lock) on rm 117, and rm 118. Repair 2x doorstops on the two doors top of lobby stairs. Bldg 0001																			
Diagnostic Fee	\$160 TW Labor 2 hours @ \$80																			
Additional Labor Cost to Perform Repairs	\$480 TW Labor 6 hours @ \$ 80																			
Additional Material Cost to Perform Repairs	<p>\$766.73</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Mortis Lockset - 35HU41</td> <td style="width: 10%;">2</td> <td style="width: 10%;">\$346.80</td> <td style="width: 10%;"></td> <td style="width: 10%;">\$693.60</td> </tr> <tr> <td>Plunger door stop - 40JK95</td> <td>2</td> <td>\$17.70</td> <td></td> <td>\$36.68</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td></td> <td>\$36.45</td> </tr> </table>					Mortis Lockset - 35HU41	2	\$346.80		\$693.60	Plunger door stop - 40JK95	2	\$17.70		\$36.68	Sales Tax				\$36.45
Mortis Lockset - 35HU41	2	\$346.80		\$693.60																
Plunger door stop - 40JK95	2	\$17.70		\$36.68																
Sales Tax				\$36.45																
Total Cost of Repair	\$1,406.73																			



# WORK ESTIMATE

CSS #:

21680

Work Order #:

11082

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Men's Restroom
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	John Brown		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace repair gang cover plate in vestibule and door handle assembly for rooms 117 and 118. Also to repair (2) door stops on the doors at top of lobby stairs.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Mortis Lockset - 35HU41	2	\$346.80		\$693.60
Plunger door stop - 40JK95	2	\$17.70		\$36.68
Sales Tax				\$36.45
Diagnostic Labor			2	\$160.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$766.73</b>	<b>Labor</b> \$640.00
		<b>TOTAL</b>		<b>\$1,406.73</b>

**ADD ALL TO CART**



GRAINGER APPROVED

**Mortise Lockset, Mechanical, Extra Heavy Duty, Keyed Different, Satin Stainless Steel**

Item # **35HU41**

Qty

2

Your Price

**\$289.00**

/ each

**ADD TO CART**



KABA ILCO

**PlungerDoorHolder, 11/16in,  
Clear Aluminum**

Item # **40JK95**

Qty

2

Your Price

**\$14.75**

/ each

**ADD TO CART**









