

## Additional Funding Request

<b>MD002</b>	<b>CSS# 22353 WO# 10126 Asset# NA</b>															
Description of Repairs	Labor and materials needed to remove and replace the faulty bulbs and ballast in the exterior pole mounted lights. Then check operation to ensure everything is working properly.															
Diagnosis: Initial Work Order	Two bulbs are out in exterior pole mounted lights															
Diagnostic Fee	\$ 300															
Additional Labor Cost to Perform Repairs	<p>\$ 800</p> <p>Labor \$100/hr x 8</p>															
Additional Cost	<p>\$ 992.16</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Bulbs and Ballast (2 EA) and tax(see quote)</td> <td style="width: 10%;">2</td> <td style="width: 15%;">\$267.16</td> <td style="width: 15%;">\$267.16</td> </tr> <tr> <td>Lift</td> <td>1</td> <td>\$675.00</td> <td>\$675.00</td> </tr> <tr> <td>Shipping</td> <td>1</td> <td>\$50.00</td> <td>\$50.00</td> </tr> </table>				Bulbs and Ballast (2 EA) and tax(see quote)	2	\$267.16	\$267.16	Lift	1	\$675.00	\$675.00	Shipping	1	\$50.00	\$50.00
Bulbs and Ballast (2 EA) and tax(see quote)	2	\$267.16	\$267.16													
Lift	1	\$675.00	\$675.00													
Shipping	1	\$50.00	\$50.00													
Total Cost of Repair	\$ 2,092.16															



## CUSTOMER QUOTATION NO. 177

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

Quote Name: 10126  
Quote No: 177  
Site: MD002 Ordnance Road  
Site Contact:  
Salesperson: Lindsay Ruby  
Created Date: 01/31/2020  
Valid For: 30 Day(s)

WO#: 10126

CSS Ticket Number: 22353

Problem: Two bulbs are out in exterior pole mounted lights.

S&S proposes to furnish and install the following:

S&S will remove the faulty bulbs and ballast in the exterior pole mounted lights.

S&S will then install two new 250 watt High Pressure Sodium Bulb and two ballast.

S&S will then check the operation to ensure everything is working properly.

### Service

Item	Quantity	Unit Price	Total
Lift	1.00	\$675.00	\$675.00
SYL Lu250 ECO	1.00	\$25.94	\$25.94
Coil Ballast	1.00	\$228.50	\$228.50
Tax	1.00	\$12.72	\$12.72
Shipping	1.00	\$50.00	\$50.00
Diagnosis Fee	1	\$300.00	\$300.00
Electrical Labor Rate	8	\$100.00	\$800.00
		<b>Sub-Total ex Tax</b>	<b>\$2,092.16</b>
		<b>Tax</b>	<b>\$0.00</b>
		<b>Total inc Tax</b>	<b>\$2,092.16</b>

Labor	\$1,100.00
Materials	\$992.16
<b>Sub-Total ex Tax</b>	<b>\$2,092.16</b>
<b>Tax</b>	<b>\$0.00</b>
<b>Total inc Tax</b>	<b>\$2,092.16</b>

**CAPITAL ELECTRIC**  
**8511 PEPCO PL**  
**UPPER MARLBORO, MD 20772-2500**  
**301-909-6500 Fax 301-736-1361**

[nichon.skinner@capitalelectricsupply.com](mailto:nichon.skinner@capitalelectricsupply.com)

QUOTE TO:  
S&S FABRICATORS INC.  
4845 SOUTH CRAIN HWY  
UPPER MARLBORO, MD 20772-3109  
240-882-1660

### Quotation

QUOTE DATE	QUOTE NUMBER
01/31/20	S039599210
	PAGE NO.
1 of 1	

SHIP TO:  
S&S FABRICATORS INC.  
4845 SOUTH CRAIN HWY  
UPPER MARLBORO, MD 20772-3109  
240-882-1660

CUSTOMER NUMBER		CUSTOMER ORDER NUMBER		JOB NAME		QUOTED TO	
SALESPERSON		SHIP VIA		FREIGHT ALLOWED		EXPIRATION DATE	
ORDER QTY	UPC	DESCRIPTION			UNIT PRICE	U	EXT PRICE
2ea	04613567578	SYL LU250/ECO (67578) CLR E18MOG HPS LAMP			10.810	e	21.62
2ea	04613547634	SYL LU250/SUPER5-KIT (47634) 5 TAP MAGNETIC CORE AND COIL BAL			95.210	e	190.42

#### TERMS & CONDITIONS

This order is subject to Company Terms and Conditions of Sale, which provisions shall govern in the event of any conflict with any Terms or Conditions of Purchaser's proposal, purchase order or other documents. All quotes/bids for Pipe and Wire are good for the date of the bid only. No extension of the pricing of these items is authorized by any employee of the Company without express written consent in the form of an official letter or signed acknowledgement of an Officer of the Company.

#### TAXES NOT INCLUDED

<b>Subtotal</b>	<b>212.04</b>
<b>S&amp;H CHGS</b>	<b>0.00</b>
<b>Amount Due</b>	<b>212.04</b>

