

Additional Funding Request

NY067	CSS# 23252 WO# 6901 Asset# NA				
Description of Repairs	Labor and Materials to replace motor on OMS Unit heater.				
Diagnosis: Initial Work Order	Unit heater in OMS shop will not run. Appears that motor has seized. Mike Moseman cell 518-421-2252				
Diagnostic Fee	\$320				
Additional Labor Cost to Perform Repairs	\$480 TW Labor 6 hours @ \$ 80				
Additional Material Cost to Perform Repairs	\$461.05				
	Modine Motor - 9F0300950000	1	\$461.05		\$461.05
Total Cost of Repair	\$1,260.05				



WORK ESTIMATE

CSS #: 23252

Work Order #: 6901

Emergency ☒

Urgent ☐

Routine ☐

Company Name:	Tidewater, Inc.	Facility ID:	NY067
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Various
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and Materials to replace motor on OMS Unit heater.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Modine Motor - 9F0300950000	1	\$461.05		\$461.05
Diagnostic Labor			4	\$320.00
SUB-TOTAL COSTS:		Materials Total	\$461.05	Labor \$800.00
TOTAL			\$1,260.05	



Customer Quotation

Ship To:

TIDEWATER INC

6625 SELNICK DR #A

ELKRIDGE, MD 21075-6220

US

Shipper Account:

Information

Grainger Quote Number	2043005885
-----------------------	------------

Print Date 01/02/2020

Customer Account	885295220
------------------	-----------

Department Number

Contact Name	PATRICK BROWN
--------------	---------------

Contact Phone	3156723272
---------------	------------

Contact Fax

Contact Email patrick.brown@tideh20.net

Requested by Brittany

Garza

Requestor Phone No.

Requestor Fax

Requestor Email Brittany.Garza@graininger.com

eQuote Information:

Quote 2043005885 has been delivered to Grainger websites and Patrick Brown has been notified via email that the quote is available for on-line purchasing.

Comments: Prior authorization is required for ALL returns; product must be new/unused and in original packaging. All returns may be subject to a restocking fee, assessed by the supplier upon inspection. Customer is responsible for return-shipping costs.

[illegible]

This is not an invoice. Changes to product or quantities may result in different pricing. Availability and lead times are subject to change and can be confirmed at order placement. Additional lead time may apply for AK and HI. Unless otherwise stated, these items are sold for domestic consumption in the United States. If exported, purchaser assumes full responsibility for compliance with U. S. export control. Contact Sales Rep. or Grainger branch listed below for questions, order placement or to submit a new request. **Return Policy: Please contact Grainger before returning any product. All returns are subject to the manufacturer's return policy. Special Order items may not be returnable. Restocking fees may apply.**

Thank You!

Call or visit us at

Graininger, Inc.

Waterloo, IA 50701-9371



D617K