

Additional Funding Request

VA048	CSS# 23506 WO# 11730 Asset# NA			
Description of Repairs	Labor and materials needed to replace the drawer on the safe in the SIPR Cafe'			
Diagnosis: Initial Work Order	FC opened the second drawer on the safe in the SIPR café. When he closed it, the handle was stuck in the down position. Needs repair.			
Diagnostic Fee	\$ 450			
Additional Labor Cost to Perform Repairs	\$ 340 Labor \$85 hr x 4			
Additional Cost	\$ 930			
	Safe Drawer	1	\$780.00	\$780.00
	Service Call	1	\$150.00	\$150.00
Total Cost of Repair	\$ 1,720.00			

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com



Estimate

Date	Estimate #
1/22/2020	29623

Customer Information

Tidewater PM
3761 Attucks Drive
Powell, OH 43065

Item	Description	Qty	Cost	Total
REPAIR	Interlock part for repair. Part isnt sold seperatly from drawer head/side tracks. Part will be removed from a new drawer head. Our price: \$650.00 x .20%	1	780.00	780.00
LABOR	Labor to install lock and weld container. One tech 4 hours @ 85 per hour (specialized GSA container tech)	4	85.00	340.00
SERVICE CALL	Service Call VA048 (CSS 23506 WO 11730) Site address: 1741 E Belt Blvd, Richmond, VA 23224	1	150.00	150.00
DIAGNOSE	VA048 GSA container check 01/23/2020 Check GSA container, have it working for now, interlock on second drawer left side needs to be welded back and replaced. Someone slammed the container casuing this issue.	1	0.00 450.00	0.00 450.00

WE LOOK FORWARD TO ASSISTING YOU!

Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.

SIGNATURE: _____

DATE: _____

Terms: Non-Refundable 50% deposit and 50% due upon completion

Subtotal

\$1,720.00

Sales Tax (0.0%)

\$0.00

Total

\$1,720.00

**Woman Owned Small Business
Small Business Enterprise**

From: [Rick Norris](#)
To: ["Hunter A"; John Kieffer](#)
Subject: RE: GSA Container Drawer Head
Date: Wednesday, January 8, 2020 11:50:53 AM
Attachments: [image004.png](#)

Hey Hunter, is this Drawer Head Legal or Letter Size? Also is it for Mosler/Diebold or Hamilton ? Lastly do you want it with or without X10? We have in stock here in MD Qty.2 that are Black, Legal, For Hamilton, Class 6, NO LOCK Part # DH1041AB which is \$658.82 each & we have Qty.1 in stock in MD that is Black, Legal, For Diebold, Class 6, NO LOCK. Part # MSK9872700BB Cost \$658.82 each.

Rick Norris
Sales Representative



Lockmasters, Inc.
12011 Guilford Road, Unit 108
Annapolis Junction, MD 20701
Tel 800-654-0637 Ext 510
RickNorris@Lockmasters.com
www.Lockmasters.com



This email and any files transmitted with it contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission.

From: Hunter A [mailto:hunter@ampmlock.com]
Sent: Wednesday, January 08, 2020 11:42 AM
To: John Kieffer <JohnKieffer@lockmasters.com>
Cc: Rick Norris <ricknorris@lockmasters.com>
Subject: Re: GSA Container Drawer Head

Awesome, need as soon as possible. Thank you!

Best Regards,
Hunter A



Small Business Enterprise
Women Owned Small Business
OFFICE: [\(410\) 764 2001](tel:4107642001)
MOBILE: [\(443\) 929 1985](tel:4439291985)



DO NOT REMOVE
THIS LABEL
OR THE
LATCH
OR THE
LATCH
OR THE
LATCH

Warning: Any modification of this container not in accordance
with Federal Standard 809 will invalidate the GSA approval
and the GSA approval label shall be removed.