

Additional Funding Request

VA049	CSS# 23919 WO# 11785 Asset# NA				
Description of Repairs	Labor and Materials to disassemble, clean flange, replace gaskets, and re assemble leaking pump.				
Diagnosis: Initial Work Order	Water pump in mechanical room is leaking. Slow steady leak. Forming puddle on floor				
Diagnostic Fee	\$240				
Additional Labor Cost to Perform Repairs	\$480 TW Labor 6 hours @ \$ 80				
Additional Material Cost to Perform Repairs	\$199.21				
	Rebuild Seal kit Bell and Gossett - 6HKZ3 (includes tax)	1	\$199.21		\$199.21
Total Cost of Repair	\$919.21				



WORK ESTIMATE

CSS #: 23919

Work Order #: 11785

Emergency ☐

Urgent ☒

Routine ☐

Company Name:	Tidewater, Inc.	Facility ID:	VA049
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Mech Room
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Richard Walker		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and Materials to disassemble, clean flange, replace gaskets, and re assemble leaking pump.


LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Rebuild Seal kit Bell and Gossett - 6HKZ3	1	\$189.72		\$189.72
Sales Tax				\$9.49
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:	Materials Total	\$199.21	Labor	\$720.00
TOTAL			\$919.21	

BELL & GOSSETT

Rebuild Seal Kit for 4RD31, 4RD67, 4RD33

Item # **6HKZ3**

Mfr Model # **180013**



Qty

1

Web Price

\$158.10 / each

Add to Cart

Add to List

AVAILABILITY

Shipping (Current Location)

Expected to arrive **Tue. Feb 11.**

Pickup (Current Location)

Richmond Branch 640

Available for pickup **Mon. Feb 10.**

Check availability at a different location

TECHNICAL SPECIFICATIONS

Item#	6HKZ3
Mfr. Model #	180013
UNSPSC #	40151504
Catalog Page	2658
Shipping Weight	0.65
Country of Origin	Mexico*
Bell & Gossett Pump Model	609PF
For Pump Number	4RD31, 4RD67, 4RD33
Gasket Type	Ethelyne/Propylene Composition
Includes	Mechanical Seal and Head, Flange Gaskets
Item	Rebuild Seal Kit

Show More

VA049
gasket leaking
from bottom



401
ETT
ORS
FIR
BLY
0.1
0.2



BEL & GOSSET 189155
MAX. LIQUID TEMP. 225°F
LUBRICATE AT INSTALLATION OR
START OF EACH HEATING SEASON
FOR CONTINUOUS SERVICE. LUBRI-
CATE EVERY 3 MONTHS WITH 3-WAY
220 OR 150W-30 OIL. DO NOT OIL
PUMP BEARINGS. USE APPROX. 10
DROPS FA.
ITT Bell & Gossett
Morton Grove, Ill. U.S.A.

GENUINE