

Additional Funding Request

DE007	CSS# 24964 WO# 12176 Asset# 1048
Description of Repairs	Labor to trouble shoot Vault at DE007
Diagnosis: Initial Work Order	Vault door is giving a fault alarm. The need is possible vault door sensor are in need of alinement.
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$720 Advanced Security 6 hours
Additional Material Cost to Perform Repairs	\$0 See attached Detail.
Total Cost of Repair	\$720.00

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com



Estimate

Date	Estimate #
5/5/2020	30049

Customer Information
Tidewater PM 3761 Attucks Drive Powell, OH 43065

Item	Description	Qty	Cost	Total
SERVICE CALL	SERVICE CALL	1	120.00	120.00
LABOR	TROUBLE SHOOT MOTION SENSOR QTY 4(J-1502000-18), ARMS VAULT 1 HOURS @ 120 PER HOUR	1	120.00	120.00
TRAVEL	TRAVEL LABOR HOURS Service Location: 1001 OGLETOWN RD NEWARK, DE 19711 CSS# 24964 WO# 12176 DE007	4	120.00	480.00

WE LOOK FORWARD TO ASSISTING YOU!

Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.

SIGNATURE: _____

DATE: _____

Terms: Non-Refundable 50% deposit and 50% due upon completion

Subtotal	\$720.00
Sales Tax (6.0%)	\$0.00
Total	\$720.00

Woman Owned Small Business
Small Business Enterprise