

Additional Funding Request

VA099	CSS# 25421 WO# 12341 Asset# NA
Description of Repairs	Labor and materials to mount safety board to concrete block in drive through bay.
Diagnosis: Initial Work Order	Mount Safety board to concrete block wall in the drive through bay
Diagnostic Fee	\$160
Additional Labor Cost to Perform Repairs	\$480 TW Labor 6 hours @ \$ 80
Additional Material Cost to Perform Repairs	\$20 Misc Materials
Total Cost of Repair	\$660



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	VA099
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Drive through bay
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	Richard Walker			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to mount safety board to concrete block in drive through bay.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Misc Materials	1	\$20.00		\$20.00
				\$0.00
				\$0.00
				\$0.00
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$20.00	Labor \$640.00
TOTAL			\$660.00	

RUBBER GLOVES

SAFETY
GOGGLES

HEARING
PROTECTION

ROPE

GROUNDING CABLE

FIRST AID KIT

SAFETY BOARD

HARD HAT

GET
PROTECTION