

Additional Funding Request

| | |
|---|--|
| NY051 | CSS# 25493 WO# 9325 Asset# 10037 |
| Description of Repairs | We were called because the dual chiller wasn't working properly. Hydestone found both surface temperature sensors and CO2 sensors need to be replaced. This pricing includes labor, materials and taxes to do the repairs. |
| Diagnosis: Initial Work Order | request to repair ac problem urgent |
| Diagnostic Fee | \$450 |
| Additional Labor Cost to Perform Repairs | \$190 2hrs @ \$95/hr |
| Additional Material Cost to Perform Repairs | \$826.24 (See attached detail) |
| Total Cost of Repair | \$1,466.24 |

**PROJECT ESTIMATE**

DATE: 06/26/2020

QUOTE ID: 5692
AR CUSTOMER: TIDE WATER, INC (#100012)
SERVICE LOCATION: U.S. ARMY RESERVE - TIDE WATER
STREET: 60 EAST 9TH STREET
CITY: OSWEGO, NY 13126

CONTACT: PATRICK BROWN - TIDE WATE
Ph:(315) 672-3272
patrickbrown2007@gmail.com
DATE SUBMITTED: 06/26/2020
PREPARED BY: Simpson, Heidi

DESCRIPTION: Temperature & CO2 Sensors

SCOPE OF WORK: We were called because the dual chiller wasn't working properly. Our technician found both surface temperature sensors and CO2 sensors need to be replaced. This pricing includes labor, materials and taxes to do the repairs. The diagnostic call is being billed separately. Please contact me to schedule this work. Thank you,
Heidi
Hyde-Stone Mechanical Contractors
22962 Murrock Circle
Watertown, New York 13601
Office: (315) 755-2283
Cell: (315) 586-2950

EQUIPMENT: Make: TRANE, M#:MCCB030UA0A0UA, S#: K04C34750, AIR HANDLER, Loc: AHU1, Eqp#: 16430

| ITEM | QUANTITY | UNIT PRICE | TOTAL |
|---------------------|----------|------------|------------|
| Labor Regular Time | 2 | \$95.00 | \$190.00 |
| Temperature Sensors | 2 | \$46.88 | \$93.76 |
| CO2 Sensors | 2 | \$297.60 | \$595.20 |
| Vehicle Charge | 1 | \$50.00 | \$50.00 |
| Environmental Fee | 1 | \$12.00 | \$12.00 |
| Tax | | | \$75.28 |
| Total | | | \$1,016.24 |

SIGNATURE

PRINT NAME

DATE





