

## Additional Funding Request

<b>VA049</b>	<b>CSS# 25661 WO# 11458 Asset# 2335</b>
Description of Repairs	Labor and materials to replace bad ignitor on Trane Package unit.
Diagnosis: Initial Work Order	Trane package unit needs new ignitor and ignition module.
Diagnostic Fee	\$160
Additional Labor Cost to Perform Repairs	\$480 TW Labor 6 hours @ \$ 80
Additional Material Cost to Perform Repairs	\$210.42  See attached Detail.
PM CREDIT	<b>(<span style="color: red;">\$250</span>)</b>
Total Cost of Repair	\$600.42



# WORK ESTIMATE

CSS #: 25661

Work Order #: 11458

Emergency  

Urgent  

Routine  

X

Company Name:	Tidewater, Inc.		Facility ID:	VA049
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Exterior Unit
E-Mail Address:	<a href="mailto:adam.cology@tideh2o.net">adam.cology@tideh2o.net</a>			
Assigned Technician(s):	Richard Walker			

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT


Labor and materials to replace bad ignitor on Trane Package unit.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Trane Ignitor Kit	1	\$210.42		\$210.42
				\$0.00
				\$0.00
				\$0.00
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$210.42	Labor \$640.00
TOTAL			\$850.42	

TRANE

## Ignitor Kit, Fits Brand Trane

Item # 30NX22 Mfr. Model # KIT3033 Catalog Page # N/A UNSPSC # 40101833

Your Price i

\$167.00 / each

 One Time Delivery Auto Reorder 1**Add to Cart**[+ Add to List](#)

Confirm ZIP Code to determine availability.

43065


**Save**

Shipping Weight 0.4 lbs.

Country of Origin USA | *Country of Origin is subject to change.**Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order. More***How can we improve our Product Images?** Compare



Voyager



Mechanical Systems  
804-299-9024  
TRANE D2

