

Additional Funding Request

DE001	CSS# 26243 WO# 127475 Asset# NA							
Description of Repairs	SS will remove and replace all lighting Ballast (5) within Vault. Will remove and replace bulbs as needed, bulbs supplied by the customer.							
Diagnosis: Initial Work Order	Most of the lights in the vault are out. Building tenants have changed out light bulbs but they are still not working. Seems like it may be ballasts that are out and need to be replaced. The main tenant unit is deployed at this time and vault access is very limited. The vault PMs are scheduled for September 9th and the vault will be opened that day, would like to schedule this work for that day as well.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 1,200</p> <p>Labor \$100/hr x 12</p>							
Additional Cost	<p>\$163.50</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33.33%;">Ballast</td> <td style="width: 33.33%;">5</td> <td style="width: 33.33%;">\$32.70</td> <td style="width: 33.33%;">\$163.50</td> </tr> </table>				Ballast	5	\$32.70	\$163.50
Ballast	5	\$32.70	\$163.50					
Total Cost of Repair	\$ 1,363.50							



S&S MECHANICAL

S&S Mechanical
4845 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 364

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 12747
Quote No: 364
Site: DE001 North New Street
Site Contact:
Salesperson: Molly King
Created Date: 09/03/2020
Valid For: 30 Day(s)

CSS 26243
WO 12747

SOW: Most of the lights in the vault are out. Building tenants have changed out light bulbs but they are still not working. Seems like it may be ballasts that are out and need to be replaced. The main tenant unit is deployed at this time and vault access is very limited. The vault PMs are scheduled for September 9th and the vault will be opened that day, would like to schedule this work for that day as well.

Quote:

S&S will remove and replace all lighting ballasts (5) within vault room.
S&S will remove and replace bulbs as needed, bulbs supplied by the customer.

Service

Item	Quantity	Unit Price	Total
Ballasts	5.00	\$32.70	\$163.50
Electrical Labor Rate	12	\$100.00	\$1,200.00
		Sub-Total ex Tax	\$1,363.50
		Tax	\$0.00
		Total inc Tax	\$1,363.50
<hr/>			
		Labor	\$1,200.00
		Materials	\$163.50
		Sub-Total ex Tax	\$1,363.50
		Tax	\$0.00
		Total inc Tax	\$1,363.50

ADVANCE Optanium, Electronic x +

https://www.grainger.com/product/ADVANCE-Optanium-36N040

All Products Bulk Order Pad

Enter keyword, item, model or replacement part number.

COVID-19 Recovery: Products and solutions to help your business move forward. [Get Started >](#)

Product Categories / Lighting / Ballasts & Drivers / Fluorescent & Compact Fluorescent (CFL) Ballasts / Non-Dimmable Fluorescent Ballasts / Electronic Fluorescent Ballasts / Optanium, Electronic, Fluorescent Ballast, B...

Customers Also Viewed

ADVANCE

Optanium, Electronic, Fluorescent Ballast, Ballast Start Type Instant

Item # 36N040 Mfr. Model # IOPA-4P32-N Catalog Page # 473 UNSPSC # 39111801

Web Price

Shipping Pickup

Expected to arrive **Fri. Sep 04.**

Ship To 20748 ([Change](#))

Shipping Weight **0.95 lbs.**

Country of Origin **Mexico** | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.

[More](#)

How can we [improve our Product Images?](#)

Compare

ADVANCE Centium™, Electronic, Fluorescent Ballast, Ballast Start Type Instant

Item # 1VN22

Web Price **\$25.25** / each

Qty

ADVANCE Centium™, Electronic, Fluorescent Ballast, Ballast Start Type Instant

Chat with an Agent

10:38 AM 9/3/2020