

Additional Funding Request

NY067	CSS# 26336 WO# 10246 Asset# NA
Description of Repairs	Labor and Materials replace mortise lockset with new on Boiler Room Door.
Diagnosis: Initial Work Order	Door handle on boiler room is loose/broken and hard to open.
Diagnostic Fee	\$240 TW Labor 3 hours @ \$ 80/hr
Additional Labor Cost to Perform Repairs	\$320 TW Labor 4 hours @ \$ 80/hr
Additional Material Cost to Perform Repairs	\$1,379.84 See attached detail
Total Cost of Repair	\$1,939.84



WORK ESTIMATE

CSS #: 26336

Work Order #: 10246

Emergency

Urgent

X

Routine

Company Name:	Tidewater, Inc.		Facility ID:	NY067
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Boiler Room Door
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	Patrick Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and Materials replace mortise lockset with new on Boiler Room Door.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			4	\$320.00
Mortise Lockset 40KA51	1	\$1,379.84		\$1,379.84
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:		Materials Total	\$1,379.84	Labor \$560.00
		TOTAL	\$1,939.84	



Roll over image to zoom.

Help us improve our Product Images

BEST

Mortise Lockset, Mechanical, Satin Chrome, 2 3/4 in Backset, Mortise

Item # 40KA51

Mfr. Model # 45H7AB3J626

UNSPSC # 46171503

Catalog Page # N/A

Country of Origin USA. Country of Origin is subject to change.

Compare this product

Web Price i

\$1,078.00 / each

Qty

1

Add to Cart

Shipping

Pickup

Ships from supplier. Expected to arrive on or before **Mon. Oct 19**.

Ship to **43065** | Change

[Ship Availability Terms](#)

Shipping Weight 6.6 lbs

Add to List



