

Additional Funding Request

VA050	CSS 26391 WO# 12759 Asset# NA							
Description of Repairs	Replace damaged cypher lock							
Diagnosis: Initial Work Order	Cypher lock is not working properly need to have combination reset.							
Diagnostic Fee	\$ 185							
Additional Labor Cost to Perform Repairs	\$ 185 Labor and trip fee							
Additional Cost	<p>\$ 750</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Cypher Lock</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">\$750.00</td> <td style="width: 30%; text-align: right;">\$750.00</td> </tr> </table>				Cypher Lock	1	\$750.00	\$750.00
Cypher Lock	1	\$750.00	\$750.00					
Total Cost of Repair	\$ 1,120.00							

Tina Lee

From: Bob Buckley <cecuritysmith@cs.com>
Sent: Tuesday, September 22, 2020 1:13 PM
To: Tina Lee
Subject: Re: CSS 26391 WO 12759 VA050

Estimate to replace pushbutton trim is \$750.00 for the trim and \$185.00 for the return visit.
The total for the return trip is \$935.00. The first trip was \$185.00.

-----Original Message-----

From: Tina Lee <tina.lee@tideh2o.net>
To: Bob BUCKLEY <cecuritysmith@cs.com>
Cc: Adam Colopy <adam.colopy@tideh2o.net>
Sent: Fri, Sep 18, 2020 10:30 am
Subject: FW: CSS 26391 WO 12759 VA050

Bob,

Your POC will be Capt. Friend she want to know if you can do Monday 9/21 after 9 am.

804-943-5142

Thank you make it a great day!

Tina M. Lee

Project Coordinator

TIDEWATER, INC.

tina.lee@tideh2o.net

C: 614-623-9569

From: Tina Lee
Sent: Friday, September 18, 2020 10:21 AM
To: Bob BUCKLEY <cecuritysmith@cs.com>
Subject: RE: CSS 26391 WO 12759 VA050

