

Additional Funding Request

MD024	CSS# 26446 WO# 13973 Asset# NA							
Description of Repairs	Labor and material to replace door closer to exterior door, across from latrine in building 1003.							
Diagnosis: Initial Work Order	Repair door closure, exterior door across from latrines, bldg 1003.							
Diagnostic Fee	\$ 160 Labor \$80/hr x 2							
Additional Labor Cost to Perform Repairs	\$ 160 Labor \$80/hr x 2							
Additional Material Cost to Perform Repairs	\$ 320 <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 5px;"> <tr> <td style="width: 50%;">Part</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">209.69</td> <td style="width: 20%; text-align: right;">209.69</td> </tr> </table>				Part	1	209.69	209.69
Part	1	209.69	209.69					
Total Cost of Repair	\$ 529.69							



WORK ESTIMATE

CSS #:

26446

Work Order #:

13973

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	MD024
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Replace door closer to exterior door, across from latrines in building 1003.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagostic			2	\$160.00
Door Closer	1	\$209.69		\$209.69
Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$209.69	Labor \$320.00
TOTAL			\$529.69	



Tap image to Zoom

NORTON DOOR CONTROLS
Manual Hydraulic Door Closer, Heavy Duty, Interior and Exterior
Item # **6T...**Mfr. Model # **8301H X 690**
UNSCSP # **3...** Catalog Group # **D1103**
Catalog Page # **1990**

Your Price
\$166.42 / each

Qty

1

Add to Cart

