

Additional Funding Request

NY127	CSS# 27022 WO# 10669 Asset# NA
Description of Repairs	Labor and Materials to replace faulty magnetic interlock switch.
Diagnosis: Initial Work Order	Vault has an error on security screen for a siren tamper.
Diagnostic Fee	\$400 TW Labor 5 hours @ \$ 80/hr
Additional Labor Cost to Perform Repairs	\$480 TW Labor 6 hours @ \$ 80/hr
Additional Material Cost to Perform Repairs	\$199.68 See attached detail
Total Cost of Repair	\$1,079.68



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	NY127
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Vault Security System
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	Patrick Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and Materials to replace faulty magnetic interlock switch.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Various Materials (See attached detail)	1	\$199.68		\$199.68
Diagnostic Labor			5	\$400.00
SUB-TOTAL COSTS:		Materials Total	\$199.68	Labor \$880.00
			TOTAL	\$1,079.68



Cart

Item	Quantity	Total Price	Item Availability
 TELEMECANIQUE SENSORS Magnetically Actuated Safety Interlock Switch, Off Sensing Distance 0.79 in, Bare Wire, 1NO/2NC Item #10D283 Your Price: \$156.00	1	\$156.00	Expected to arrive Thu. Oct 22 using standard ground shipping (additional shipping options available at Checkout.)

This item can only be sent via ground shipping.

 Chat with an Agent

55F NO
4-Q-11
ULC
UL