

## Additional Funding Request

<b>NY067</b>	<b>CSS# 27205 WO# 10678 Asset# NA</b>
Description of Repairs	Labor and materials to replace OMRON Photoelectric Sensor on gate.
Diagnosis: Initial Work Order	Repair MEP lot gate will not open. The error code that comes up on screen says "PEC Active".
Diagnostic Fee	\$240  TW Labor 3 hours @ \$ 80/hr
Additional Labor Cost to Perform Repairs	\$320  TW Labor 4 hours @ \$ 80/hr
Additional Material Cost to Perform Repairs	\$506.88  OMRON Photoelectric Sensor
<b>Total Cost of Repair</b>	<b>\$1,066.88</b>



# WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	NY067
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Gate
E-Mail Address:	<a href="mailto:adam.cology@tideh2o.net">adam.cology@tideh2o.net</a>			
Assigned Technician(s):	Patrick Brown			

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace OMRON Photoelectric Sensor on gate.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			4	\$320.00
OMRON Photoelectric Sensor	1	\$506.88		\$506.88
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:		Materials Total	\$506.88	Labor \$560.00
TOTAL			\$1,066.88	



# Cart

Item	Quantity	Total Price	Item Availability
 <b>OMRON 185 mm Selectable Light</b> On/Dark On Rectangular Photoelectric Sensor; Sensing Method: Retroreflective Item #2A183 Your Price: <b>\$396.00</b>	1	<b>\$396.00</b>	Expected to arrive <b>Fri. Oct 23</b> using standard ground shipping (additional shipping options available at Checkout.)

 Chat with an Agent

