

## Additional Funding Request

<b>VA048</b>	<b>CSS# 28061 WO# 13328 Asset# NA</b>							
Description of Repairs	Labor and materials to replace leaking ¼ in saddle valve on hot water supply line.							
Diagnosis: Initial Work Order	Water is leaking from the roof or pipes above the cage in the AMSA bay area to the floor.							
Diagnostic Fee	<p>\$ 240</p> <p>Labor \$80/hr x 3</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 640</p> <p>Labor \$80/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 70.06</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Parts (see detail in quote)</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: center;">70.06</td> <td style="width: 30%; text-align: center;">70.06</td> </tr> </table>				Parts (see detail in quote)	1	70.06	70.06
Parts (see detail in quote)	1	70.06	70.06					
Total Cost of Repair	\$ 950.06							



# WORK ESTIMATE

CSS #:

28061

Work Order #:

13328

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	VA048
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	Richard Walker		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace leaking 1/4 in saddle valve on hot water supply line.

LABOR/MATERIAL		MATERIAL/SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Parts (See detail in quote)	5			\$70.06
				\$0.00
				\$0.00
				\$0.00
Diagnostic Labor			3	\$240.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$70.06</b>	<b>Labor</b> \$880.00
		<b>TOTAL</b>		<b>\$950.06</b>



Enter keyword, item, model or part #

**Check Availability**

Enter U.S. ZIP

**GO****Saddle Valves**

ANDERSON METALS

Nonself-Piercing Saddle Valve, 1/4

In

Item # **4GU26**Mfr. Model # **4GU26**

Qty

1

Web Price

**\$14.34** / each**Check Availability****ADD TO CART****ADD TO LIST****SHARE THIS PRODUCT**

## Caulks and Sealants

DOW CORNING

White Sealant, Silicone, 10.1 oz

Item # 53DA96

Mfr. Model # 1892118



Qty

1

Web Price

**\$11.07** / each

[Check Availability](#)

[ADD TO CART](#)

[ADD TO LIST](#)

[SHARE THIS PRODUCT](#)



### Product Details

Dow Corning® silicone-based sealant for industrial assembly and maintenance lasts longer and is more

[Show More ▾](#)

Technical Specifications

## Pipe Insulation

K-FLEX USA

1/2 in Thick, Pre-Slit/Pre-Glued with Overlap NBR/PVC Pipe Insulation, 6 ft Insulation Length

Item # 40PN71

Mfr. Model # 6RXL0048058



Qty  
1

Web Price  
**\$7.35** / each

This item requires special shipping, additional charges may apply.

[Check Availability](#)

[ADD TO CART](#)

[ADD TO LIST](#)

[SHARE THIS PRODUCT](#)



[Product Details](#)

Tape, 0° to 150°F

Item # 6WXE4

Mfr. Model # 627371



Qty  
1

Web Price  
**\$11.78** / each

[Check Availability](#)

[ADD TO CART](#)

[ADD TO LIST](#)

[SHARE THIS PRODUCT](#)









VA048 AMSA shop  
Above electrical room/office  
Leak from hw supply tap

