

Additional Funding Request
INVOICE

VA048	CSS# 28365 WO# 13453 Asset# NA							
Description of Repairs	LoCurrent Systems arrived on site to diagnose as per SOW "AMSA gate has no power". While on site diagnosing, found Loop Detector Module to be nonfunctional. Replaced Loop Detector Module and 3 AMP Fuse while on site. Gate is 100% operational.							
Diagnosis: Initial Work Order	AMSA gate has no power.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 650</p> <p>LoCurrent 2x men \$75/hr x 4</p> <p>Admin Fee \$50</p>							
Additional Cost	<p>\$ 200</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Loop Detector Module</td> <td style="width: 10%;">1</td> <td style="width: 20%;">200.00</td> <td style="width: 30%;">200.00</td> </tr> </table>				Loop Detector Module	1	200.00	200.00
Loop Detector Module	1	200.00	200.00					
Total Cost of Repair	\$ 850.00							

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

INVOICE # 1831
DATE 01/11/2021
DUE DATE 02/10/2021
TERMS Net 30

P.O. NUMBER

Monteith VA048 AMSA Gate Repair

ACTIVITY	QTY	RATE	AMOUNT
Installation	1	850.00	850.00
Monteith VA048			
Repaired AMSA Gate			

LoCurrent Systems arrived on site to diagnose as per SOW: "AMSA gate has no power". While on site diagnosing, found Loop Detector Module to be nonfunctional. Replaced Loop Detector Module and 3 AMP Fuse while on site. Gate is 100% Operational.

Cost Breakdown:

(2) men 4 hrs @ \$75.....	\$600.00
(1) Loop Detector Module.....	\$200.00
Administrative.....	\$50.00
 Grand Total.....	 \$850.00

The cost for the above mentioned is \$850.00.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

\$850.00

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA - 048

Date of Visit: 1-10-21

Contractor Personnel on Site:

1. Keith Pearson
2. Chris Denike
3. _____
4. _____
5. _____
6. _____

Service Calls – Service Call Number and Description


1. EST - 1716
2. CSS - 28365
3. WO - 13452

AMSA GATE

Diagnosed & Replaced defective loop Detector module
CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Keith Pearson Date: 1-10-21

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: NO ONE Available

E-Mail: _____

